## INDEX

## SERVICE BULLETINS - 1973

SUBJECT	APPLICATION	NO.
TECHNICAL		
Engine:		
1750 c.c. Crankshaft Oil Consumption - V8	Marina P76	2 17
Campaign 2T2Y - Muffler Heat	P76 -	= 4
Shield Installation.	All Models	23
Oil Pressure Relief Valve	2600 cc OHC ) E6 Marina & P76 )	35
Oil Consumption	P76 - V8	41
<u>Fuel System</u> :		
Vapour Lock	P76 (6 Cyl.)	33
Transmission:		
Transmission	Morris 1500	7
Wheel Cylinder Connecting Pipe/ C.V. Joint Boot	Mini Dange	0
Road Wheels & Wheel Nuts	Mini Range Leyland Mini S	10
Propeller Shaft	Marina	13
Automatic Transmission Dipstick Front Wheel Bearing Adjustment	P76 Marina )	25
Timing Chain Tensioner	Mini Range & Moke)	32
Drive Shaft - Campaign 4L1Y	Mini	44
Suspension:		7.7
Shock Absorber Replacement	Marina	1
Suspension	Marina	5
Suspension Warranty Procedure - Armstrong	Marina	8
York Shock Absorbers.		19
Upper Ball Joint Sealing	Maraina	20
Front Suspension Swivel Pin. Front Suspension Crossmember	Marina	29
Mounting.	P76	34
Steering:		
Stiff Steering	P76	21
Swivel Pin Identification	Marina	39

SUBJECT	APPLICATION	NO.
Braking System :  Clutch & Brake Pedal Squeak Brake Pipe Assembly	P76 Marina (150-OHC, 175-OHC & 262 SIX)	24
Electrical & Instruments:		
Wiring Harness Chafing Wiring - Windscreen Wiper Motor Ignition Warning Light Glowing Intermittent Starter Solenoid Operation. Battery Cables Wiper Arm and Blade Fitting Starter Solenoid Relay	Morris Marina Model - P76 P76 P76 P76 P76 P76 P76	4 16 26 27 28 31 37
Body & Fittings:  Windscreen and Backlight Sealing Water Sealing Swing Arm Exterior Mirror Clips and Body Fixings Muffler to Floor Pan Clearance Body Sealing Heavy Duty Protection Kit Door Glass Guide Refitting and use of Approved Adhesives. Mat Black Paint	Morris Marina Marina All Models P76 P76 (6 Cyl.) P76 P76 P76	6 11 12 20 22 30 36 40 42
Miscellaneous:  Important Maintenance Service Check  P76 Release - Service Arrangements Speedo Head to Model Identification.	Morris 1500/ 1300 and Nomad	3 15 18
Tools :		
Leyland P76 Service Tools		14
Air Conditioning:  P.76 Air Conditioning Installation	P.76	43