

**Service Bulletin Index  
1975**

**Page 1 Missing**

SUBJECT	APPLICATION	NO.
<u>Electrical &amp; Instruments</u>		
Reverse Light Switch-Intermittent	P76/Marina	4
Starter Solenoid Operation	P76/Marina	4
Difficult Starting	Marina Auto 4 cyl	7
Speedometer Flexible Drive Cable	Mini (Saloon & Van)	12
Spark Plugs	Triumph Dolomite	24
Overdrive Switch	Triumph Dolomite	24
Windscreen Wipers	Buffalo	29
Lucas Ignitest-Test Equipment	All Models	33
Battery Carrier	Mastiff	34
<u>Body &amp; Fittings</u>		
Water Entry via Heater Fan.	P76	3
Hood Discolouration	Triumph Stag	10
Seat Belts - CAMPAIGN	Triumph	15
Seat Adjustments	Mini	18
<u>Miscellaneous</u>		
U.K. Service Information (incl. Index)	Triumph	11
U.K. Service Information (incl. Index)	Rover	16

SUBJECT	APPLICATION	NO.
<u>ADMINISTRATION</u>		
Service Policy & Warranty Procedure		1
Workshop Manual TP686	Marina	2
Service Charges-1000 mls/1500 km	All Models	3
Newcell Radiator Warranty	Marina	4
Technical Publications & Literature		5
Workshop Manual 607202	Rover 3500/3500S	6
Warranty Claim Procedure-Paint	All Models	7
New Vehicle Registration Cards R034	All Models	8
Warranty Claim Reimbursement Rates	Trucks & Tractors	9
Integrated Warranty Claim Procedure	All Models	10
Transit damage/Loss Claim Procedure	All Models	11
Customer Service Operations		12
Special Tools	All Models	13
<u>SERVICE LETTERS</u>		
Service Bulletins	All Models	5/12/75